


## Fixing manual for 24250




STEP2:Install the slide on the side board by 6pcs




STEP4:Drilling 6 pcs  $\Phi2.5$  hole on the



STEP1:Drilling 6pcs Φ2.5 hole on the cabient





STEP 5:Install the front board by 6pcs ST3.5\*16 screw

